Owner Name and Address: Ben E Arps Exxon PO Box 58 Augusta MT 59410 Phone: (406) 562-3377

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2502114	Augusta Service Station LLP	Main St	Augusta	59410	(406) 562-3377

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
1 / 06 Currently in Use	3950	6/6/1989 17 / No	Diesel 1,500	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	ABCDEFGH●J&L B DEFGH 1J ® ●	No Yes Yes Yes
2 / 05 Currently in Use	3951	6/6/1989 17 / No	Gasoline 750	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	B DEFGHOUK B DEFGHOUK	No Yes Yes Yes
6 / 04 Currently in Use	3952	6/6/1989 17 / No	Gasoline 750	Composite (Steel w/ FRP) None	Fiberglass Reinforced Plastic Cathodically Protected	Safe Suction	ABCDEFGHOJKL B DEFGHIJK	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 1 of 71

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2509034	Malmstrom AFB F 5	MT Highway 21	Augusta	59410	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	247	5/1/1992 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF®HIJKL B DEF®HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 2 of 71

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2509035	Malmstrom AFB F 6	US Highway 287	Augusta	59410	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	248 5/1/1992 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 3 of 71

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2509036	Malmstrom AFB F 7	Road 434	 Augusta	59410	

TankID/Alt TankID Status	NI	nstalled Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	249 6/1	/1992 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.I.K.L.	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 4 of 71

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2509049	Malmstrom AFB G 9	US Highway 287	Augusta	59410	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	254	10/1/1991 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed	

Report Generation Date: 7/3/2006 Page 5 of 71

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2509050	Malmstrom AFB G 10	US Highway 287	Augusta	59410	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	255 6/	/1/1992 14 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 6 of 71

Owner Name and Address: 341 CES CEV 39 78th St N Malmstrom A F B MT 59402 Phone: (406) 731-6369

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5009030	Malmstrom AFB F 1	US Highway 287	Augusta	59410		•

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	303 (6/2/1962 44 / No	Diesel 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	U.S. Suction	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 7 of 71

Owner Name and Address: Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2500098	Noons 415	200 Montana Ave	 East Helena	59635	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of U		1/1/1980 26 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized		Yes Yes Yes Yes
2 / 02 Temporarily Out of U		1/1/1980 26 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Lined Interior/Impressed Curr	Galvanized Steel Impressed Current	Pressurized	● ● E F G H ● J K L	Yes Yes Yes Yes
3 / 03 Temporarily Out of U		10/1/1995 10 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Impressed Current	Pressurized	ABCDEF@H⊕J&L ● ● EF @ H● J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 8 of 71

Owner Name and Address: Canyon Ferry Mini Basket Inc 3012 Canyon Ferry Road East Helena MT 59635 Phone: (406) 227-8506

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2503122	Canyon Ferry Mini Basket Inc	3012 Canyon Ferry Road	East Helena	59635	(406) 227-8506

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2319	6/1/1994 12 / No	Gasoline 10,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL OEFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	2320	5/5/1985 21 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGHIJKL (D) (D) (E) (B) (D) (C) (D) (D) (D) (D) (D) (D) (D) (D) (D) (D	Yes Yes Yes Yes
3 / 03 Currently in Use	2321	5/5/1985 21 / No	Diesel 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 9 of 71

Owner Name and Address: Ed Prebil PO Box 310 East Helena MT 59635 Phone: (406) 227-6211

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2503907	Eds Sinclair Service East Helena	201 W Main St	East Helena	59635	(406) 227-6211

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently in Use	856	1/1/1990 16 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	857	1/1/1990 16 / No	Gasoline 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKU • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
6 / 06 Currently in Use	858	1/1/1990 16 / No	Gasoline 8,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL O OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 10 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2508697	Town Pump Inc East Helena	418 W Main St	East Helena	59635	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4672	4/14/1968 38 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABCOEFGHIJKL</pre>	Yes Yes Yes Yes
2 / 02 Currently in Use	4673	4/14/1968 38 / No	Gasoline 12,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
3 / 03 Currently in Use	4674	4/14/1968 38 / No	Diesel 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHUJKL • • EFGHUJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	4675	4/14/1968 38 / No	Diesel 3,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHUJKL • • EFGHUJKL	Yes Yes Yes Yes
5 / 05 Currently in Use	4676	4/14/1968 38 / No	Gasoline 4,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHUUKU • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
6 / 06 Currently in Use	4677	4/14/1977 29 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHUUKU • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes
7 / 07 Currently in Use	4678	4/14/1977 29 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 11 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613915	Town Pump Inc East Helena 2	116 Lane Ave	East Helena	59635	(406) 227-9170

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4028	12/1/1998 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC • E F • H 1 J & L B D E F • H 1 J & L	Yes Yes Yes Yes
2 / 02 Currently In Use	4029	12/1/1998 07 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)JKL B (DEFOH)JKL	Yes Yes Yes Yes
3 / 03 Currently In Use	4030	12/1/1998 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH) (K) (B (DEFOH) (K)	Yes Yes Yes Yes
4 / 04 Currently In Use	4031	12/1/1998 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized		Yes Yes Yes Yes
5 / 05 Currently In Use	4032	12/1/1998 07 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized		Yes Yes Yes Yes
6 / 06 Currently In Use	4033	3/1/1999 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)JKL B (DEFOH)JKL	Yes Yes Yes Yes
7 / 07 Currently In Use	4861	8/18/2003 02 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B (DEFOHIJKL)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 12 of 71

Owner Name and Address: ECS No 6 Army Reserve 2150 Williams St Helena MT 59602 Phone: (406) 442-1112

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2500217	ECS 6 Army Reserve	2150 Williams St	Helena	59602	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02	12/1/1995	Other	Composite (Steel w/ FRP)	No Piping	Not Listed	(ABCDEFGH)J.L	Yes
Currently in Use	10 / No	200	Double-Walled	None		(B DEFGH)J.L	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 13 of 71

Owner Name and Address: Exec Air Montana Inc 2560 Airport Road Helena MT 59601 Phone: (406) 442-2190

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	
2500642	Exec Air Montana Inc 1	2430 Airport Road	_	Helena	59601		_

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently in Use	3344	6/1/1991 15 / No	Other 12,000	STI-P3 Double-Walled	No Piping None	Gravity Feed	8 DEFGHIJKL B DEFGHIJKL	Yes Yes Yes Yes
6 / 06 Currently in Use	3345	6/1/1991 15 / No	Other 12,000	STI-P3 Double-Walled	No Piping None	Pressurized	(ABCDEF@H)JKL (B DEFGH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 14 of 71

Owner Name and Address: Lewis & Clark County Jail 228 E Broadway St Rm 5 Helena MT 59601 Phone: (406) 447-8299

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2500945	Combined Criminal Justice Facility	221 Breckenridge St	Helena	59601	(406) 447-8299

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	4060 4/21/1985	Diesel	STI-P3	Flexible Plastic	U.S. Suction	ABCOEFGHIJKU	Yes
Currently in Use	21 / No	3,000	None	Double-Walled		B DEFOHIJKU	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 15 of 71

Owner Name and Address: Greg & Maryann Axtman 8227 Canyon Ferry Road Helena MT 59602 Phone: (406) 475-3195

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2501091	Kims Marina & Resort	8015 Canyon Ferry Road	Helena	59602	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently in Use	3516	5/1/1993 13 / No	Gasoline 3,782	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	8 DEF®HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 16 of 71

Owner Name and Address: Northwestern Corp 40 E Broadway St Butte MT 59701 Phone: (406) 497-3000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2501183	Helena Service Center	1315 N Last Chance Gulch St	Helena	59601	(406) 467-2669

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 04 Currently In Use	1678	5/1/1998 08 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	8 DEF@HIJKL	Yes Yes Yes Yes
5 / 05 Currently In Use	1679	5/1/1998 08 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	8 DEF 0 H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 17 of 71

Owner Name and Address: Associated Food Stores Inc PO Box 4069 Helena MT 59604 Phone: (406) 442-3140

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2501273	Associated Food Stores Inc Helena	2705 Airport Road	Helena	59601	(406) 442-3140	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
7 / 07 Currently In Use	4534	5/18/2001 05 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
8 / 08 Currently In Use	4535	5/18/2001 05 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL (B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 18 of 71

Owner Name and Address: Barb Leland 1831 11th Ave Helena MT 59601 Phone: (406) 442-4865

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2501314	Friendlys Sinclair	1831 11th Ave	Helena	59601	(406) 442-4865

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently In Use	4611	1/2/2002 04 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H J J K L B • E F • H J J K L	No Yes Yes Yes
6 / 06 Currently In Use	4612	1/2/2002 04 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B	No Yes Yes Yes
7 / 07 Currently In Use	4613	1/2/2002 04 / No	Gasoline 20,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHJJKU • DEFOHJJKU	No Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 19 of 71

Owner Name and Address: Allen Oil Co Inc PO Box 5990 Helena MT 59604 Phone: (406) 442-9290

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2501315	Junction Ethanol Card Stop	1330 N Montana Ave	Helena	59601	(406) 443-5098

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	369	8/30/1998 07 / No	Gasoline 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently In Use	370	8/30/1998 07 / No	Gasoline 5,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC●EFGHIJKL B ●EFGHIJKL	Yes Yes Yes Yes
5 / 05 Currently In Use	371	8/30/1998 07 / No	Other 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B OEFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 20 of 71

Owner Name and Address: Conoco Inc PO Box 30198 Billings MT 59107 Phone: (406) 225-2626

			_				
Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	
2501846	Conoco Phillips Terminal Helena	3180 US Highway 12 E		Helena	59601	(406) 442-6395	
		PO Box 30198					

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 39 Currently in Use	4919	1/1/1993 13 / No	Mixture 10,000	Fiberglass Reinforced Plastic Double-Walled	Bare Steel Impressed Current	Gravity Feed	ABCDEF • H 1 J K L B DEF G H 1 • K L	Yes Yes Yes Yes
9 / S30IN Currently in Use	725	1/1/1953 53 / Ye	Kerosene 840,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	ABCDEFGH() • DEFGH()	Yes Yes Yes Yes
10 / S30OUT Currently in Use	4259	1/1/1953 53 / Ye	Kerosene 840,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	<pre>ABCDEFGH().€L</pre> ● DEFGH().€KL	Yes Yes Yes Yes
11 / S35IN Currently in Use	734	1/1/1959 47 / Ye	Gasoline 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	ABCDEFGHIJKO	Yes Yes Yes Yes
12 / S31IN Currently in Use	727	1/1/1953 53 / Ye	Diesel 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGHIJK) (DEFGHI)(K)	Yes Yes Yes Yes
13 / S32IN Currently in Use	729	1/1/1953 53 / Ye	Gasoline 840,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGHIJEL) (DEFGHIERL)	Yes Yes Yes Yes
14 / S33IN Currently in Use	731	1/1/1953 53 / Ye	Gasoline 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGHIJK) (DEFGHI)(K)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 21 of 71

15 / S35OUT Currently in Use	733 1/1/1959 47 / Ye	Gasoline 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	<pre></pre>	Yes Yes Yes Yes
16 / S36IN Currently in Use	735 1/1/1959 47 / Ye	Gasoline 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH)(KO (DEFGH)(KL)	Yes Yes Yes Yes
17 / S31OUT Currently in Use	728 1/1/1953 53 / Ye	Diesel 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH) (KO) (DEFGH) (KO)	Yes Yes Yes Yes
18 / S36OUT Currently in Use	736 1/1/1959 47 / Ye	Gasoline 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH) (KD) (DEFGH) (KL)	Yes Yes Yes Yes
25 / S32OUT Currently in Use		Gasoline 840,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH) (BL) (BCDEFGH) (BC)	Yes Yes Yes Yes
26 / S37PIPE Currently in Use	737 1/1/1953 53 / Ye	Diesel 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGH) (BL) (B)	Yes Yes Yes Yes
27 / S33OUT Currently in Use	732 1/1/1953 53 / Ye	Gasoline 1,260,000	Unknown None	Galvanized Steel Impressed Current	Pressurized	(ABCDEFGHIJKO (DEFGHIOKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 22 of 71

Owner Name and Address: Sinclair Marketing, Inc 550 E S Temple PO Box 30825 Salt Lake City UT 84130 Phone: (801) 524-2700

Sys Fac I	Location Name	Location Street Address		Location City	Zip	Location Phone	
2502093	Sinclair Retail 25009	1800 Prospect Ave	_	Helena	59601		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 08 Currently in Use	1946	10/1/1993 12 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B	Yes Yes Yes Yes
2 / 06 Currently in Use	1944	10/1/1993 12 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes
3 / 07 Currently in Use	1945	10/1/1993 12 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 23 of 71

Owner Name and Address: Exec Air Montana Inc 2560 Airport Road Helena MT 59601 Phone: (406) 442-2190

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2502123	Exec Air Montana Inc 2	2430 Airport Road	Helena	59601	(406) 442-2190

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3646	4/1/1966 40 / No	Other 15,000	Asphalt Coated or Bare Steel Impressed Current	No Piping None	Not Listed	ABCDOFGHIJKL B DEFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	3647	4/1/1966 40 / No	Other 15,000	Asphalt Coated or Bare Steel Impressed Current	No Piping None	Not Listed	B DEFGHIJKL	Yes Yes Yes Yes
3 / 03 Currently in Use	3648	4/1/1966 40 / No	Gasoline 15,000	Asphalt Coated or Bare Steel Impressed Current	No Piping None	Not Listed	ABCD®FGHJJKL B DEFGHJJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3649	4/1/1966 40 / No	Gasoline 15,000	Asphalt Coated or Bare Steel Impressed Current	No Piping None	Not Listed	ABCD®F@HIJKL B DEF@HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 24 of 71

Owner Name and Address: Tray LLC 1701 Cedar St Helena MT 59601 Phone: (406) 450-6297

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2503466	Gabes Convenience Store	1701 Cedar St	Helena	59601	(406) 443-3760

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently In Use	2228	9/1/1998 07 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes
6 / 06 Currently In Use	2229	9/1/1998 07 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)JKL (B OEFOH)JKL	Yes Yes Yes Yes
7 / 07 Currently In Use	2230	9/1/1998 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 25 of 71

Owner Name and Address: United Parcel Service 547 S 20th St W Ste 6 Billings MT 59102 Phone: (406) 656-8964

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2504538	United Parcel Service Helena	3029 Airport Road	Helena	59601	(406) 449-3505

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
5 / 05 Currently in Use	4446	12/1/1993 12 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCOEFOHIJ&L B DEFOHIJ&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 26 of 71

Owner Name and Address: Stockton Oil Co 1607 4th Ave N PO Box 1756 Billings MT 59103 Phone: (406) 245-6376

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2504966	Jolly Os Gas N Go	1200 Cedar St	Helena	59601	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4784	3/26/1985 21 / No	Gasoline 8,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	(ABCDEFGHOJKL) (BCDEFGHOJKL)	Yes Yes Yes Yes
2 / 02 Currently in Use	4785	3/26/1985 21 / No	Gasoline 8,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	(ABCDEFGHOJKL) (BCDEFGHOJKL)	Yes Yes Yes Yes
4 / 04 Currently in Use	4786	9/1/1991 14 / No	Gasoline 4,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABCDEFGHOJKL • • EFGHOJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 27 of 71

Owner Name and Address: Jerry Fetters 1901 N Last Chance Gulch ST Helena MT 59601 Phone: (406) 442-5087

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505099	Jerrys Hiway Service	1901 N Last Chance Gulch St	Helena	59601	(406) 442-5087

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	1053	11/22/1972 33 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	B D E F ⊕ H 1 J K L B D E F ⊕ H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	4419	11/22/1972 33 / No	Diesel 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	B DEEGHIJKT	Yes Yes Yes Yes
3 / 03 Currently in Use	1055	11/22/1972 33 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 28 of 71

Owner Name and Address: Helena School Dist 1 55 S Rodney St Helena MT 59601 Phone: (406) 447-8887

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505142	Helena School Dist 1	1200 N Sanders St	Helena	59601	(406) 447-8887

TankID/Alt TankID Status	Tag Install Numbe Age/A		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
3 / 03 Currently In Use	1295 8/1/1997	Gasoline No 2,000	Cathodically Protected Steel Double-Walled	Flexible Plastic Double-Walled	Safe Suction	$\begin{array}{cccccccccccccccccccccccccccccccccccc$	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 29 of 71

Owner Name and Address: JTA Inc 3300 Green Meadow Dr Helena MT 59602 Phone: (406) 442-7095

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505688	Green Meadow Market	3300 Green Meadow Dr	Helena	59602	(406) 442-7095

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3243	10/1/1979 26 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABC● E F G H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	3244	10/1/1979 26 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHJJKU • • EFGHJJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 30 of 71

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505774	Kum and Go Store 894	1318 Euclid Ave	Helena	59601	(406) 442-9402

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 Currently in Use	4518	4/26/1984 22 / No	Gasoline 6,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL O OEFGHIJKL	Yes Yes Yes Yes
2 / 01 Currently in Use	4519	4/26/1983 23 / No	Gasoline 10,000	Asphalt Coated or Bare Steel Impressed Current	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGHIJKU	Yes Yes Yes Yes
4 / 04 Currently In Use	4520	4/23/1997 09 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● ●EFGHIJKL</pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 31 of 71

Owner Name and Address: Veterans Administration VA Center Fort Harrison MT 59636 Phone: (406) 442-6410

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505908	Veterans Health Administration	Williams St & Birdseye Road	Helena	59602	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 09 Currently in Use	2215	11/30/1993 12 / No	Diesel 2,500	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B DEF.H.J.K.L	Yes Yes Yes Yes
3 / 08 Currently in Use	2214	12/1/1993 12 / No	Gasoline 1,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B DEF 0 H 1 J K L	Yes Yes Yes Yes
7 / 10 Currently in Use	2216	12/1/1993 12 / No	Diesel 4,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	U.S. Suction	B D E F ● H 1 J K L	Yes Yes Yes Yes
8 / 11 Currently in Use	2217	12/1/1993 12 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	B DEF H 1 J K L	Yes Yes Yes Yes
9 / 12 Currently in Use	2218	12/1/1993 12 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	U.S. Suction	ABCDEF.H.J.K.L B.DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 32 of 71

Owner Name and Address: Big Sky Ready Mix Inc PO Box 5960 Helena MT 59604 Phone: (406) 227-8585

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505993	Big Sky Ready Mix Inc	2930 Canyon Ferry Road	Helena	59602	(406) 227-8585

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	446	5/1/1994 12 / No	Diesel 8,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	ABCDEF•H1JKL B DEFGH1•KL	Yes Yes Yes Yes
4 / 04 Currently in Use	447	5/1/1994 12 / No	Gasoline 2,000	Cathodically Protected Steel Double-Walled	Fiberglass Reinforced Plastic None	Safe Suction	(ABCDEF.H).KL B DEFGH).KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Causing	C Inventory Control	- Vapor Manitoring	G Interstit, Dbl-Wall Monitor	SIR	K Deferred
A Manual Tank Gauging	, , , , , , , , , , , , , , , , , , , ,	E Vapor Monitoring			K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed

Report Generation Date: 7/3/2006 Page 33 of 71

Owner Name and Address: Gates of The Mountains Inc PO Box 4478 Helena MT 59604 Phone: (406) 458-5241

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2506619	Gates of the Mountains Inc		Helena	59601	(406) 458-5241

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	1202	4/29/1986 20 / No	Gasoline 5,000	STI-P3 Double-Walled	Galvanized Steel Impressed Current	Pressurized		Yes Yes Yes Yes
4 / 04 Currently in Use	1203	4/29/1986 20 / No	Diesel 1,000	STI-P3 Double-Walled	Galvanized Steel Impressed Current	Pressurized	(ABCDEF.H).KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	T SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 34 of 71

Owner Name and Address: Montana Department of Deadhead Helena MT 59620 Phone: (406) 444-6200

Transportation

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2506849	MDOT Helena Headquarters	2701 Prospect Ave	Helena	59601	(406) 444-6163

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/Overl/C
4 / 04 Currently In Use	2911 3	3/1/1996 10 / No	Diesel 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABC • EF • H 1 J & L B D E F • H 1 J & L	Yes Yes Yes Yes
5 / 05 Currently in Use	2912 3	3/1/1996 10 / No	Gasoline 12,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 35 of 71

Owner Name and Address: L&B LLP DBA Souths Country Store 3487 Birkland Dr Helena MT 59602 Phone: (406) 227-5757

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2507353	Souths Country Store	3105 York Road	Helena	59602	(406) 227-5757

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 05 Currently in Use	3562	5/1/1993 13 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized		Yes Yes Yes Yes
4 / 06 Currently in Use	3563	5/1/1993 13 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKU • • EFGHIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 36 of 71

Owner Name and Address: Bobs Valley Service Inc 7507 N Montana Ave Helena MT 59602 Phone: (406) 458-5140

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2507404	Bobs Valley Service Inc UST	7507 N Montana Ave	Helena	59602	(406) 458-5140

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
4 / 05 Temporarily Out of U		3/27/1988 18 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
5 / 06 Currently in Use	475	3/27/1988 18 / No	Gasoline 6,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	8 DEF 0 H 1 J K L	Yes Yes Yes Yes
6 / 07 Currently in Use	476	6/1/1992 14 / No	Diesel 8,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC●EFGHIJKL B DEF●HIJKL	Yes Yes Yes Yes
7 / 08 Currently In Use	477	11/15/1998 07 / No	Gasoline 20,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC®EF@HIJKL B DEF®HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 37 of 71

Owner Name and Address: Timothy C Hornbacher 1721 Cedar St Helena MT 59601 Phone: (406) 442-0540

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2507848	Tims Exxon	1721 Cedar St	Helena	59601	(406) 442-0540

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 08 Currently in Use	1399	11/1/1990 15 / No	Used Oil 1,000	Cathodically Protected Steel None	Fiberglass Reinforced Plastic None	Gravity Feed	● B C D E F G H () J Ø L● D E F G H () J Ø L	Yes Yes Yes Yes
3 / 06 Currently in Use	1398	12/29/1987 18 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	B • E F G H 1 J K L	Yes Yes Yes Yes
4 / 04 Currently in Use	1396	12/29/1987 18 / No	Gasoline 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	(ABC●EFGH)J&L B ●EFGH)J&L	Yes Yes Yes Yes
5 / 05 Currently in Use	1397	12/29/1987 18 / No	Diesel 10,000	STI-P3 None	Galvanized Steel Cathodically Protected	Pressurized	(ABC●EFGHIJKL B ●EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 38 of 71

Owner Name and Address: Sutey Oil Co Inc 2000 Holmes Ave Butte MT 59701 Phone: (406) 494-2305

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2507931	Thriftway Super Stop 9	1405 Euclid Ave	Helena	59601	(406) 449-0017

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
6 / 06 Currently in Use	2056	9/1/1996 09 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
7 / 07 Currently in Use	2057	9/1/1996 09 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKL	Yes Yes Yes Yes
8 / 08 Currently in Use	2058	9/1/1996 09 / No	Diesel 6,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC@EF@HIJ&L B DEF@HIJ&L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 39 of 71

Owner Name and Address: Rocky Mountain Oil Co Inc 4567 W 80th St PO Box 1224 Minneapolis MN 55440 Phone: (952) 830-8891

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2508067	Holiday Stationstore 270	401 Euclid Ave	Helena	59601	(406) 443-0135

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	3017	5/1/1987 19 / No	Gasoline 12,000	STI-P3 Impressed Current	Bare Steel Cathodically Protected	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
2 / 02 Currently in Use	3018	5/1/1987 19 / No	Diesel 10,000	STI-P3 Impressed Current	Bare Steel Cathodically Protected	Pressurized	<pre></pre>	Yes Yes Yes Yes
3 / 03 Currently in Use	3019	11/1/1987 18 / No	Gasoline 10,000	STI-P3 Impressed Current	Bare Steel Cathodically Protected	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
4 / 04 Currently in Use	3020	11/1/1987 18 / No	Gasoline 10,000	STI-P3 Impressed Current	Bare Steel Cathodically Protected	Pressurized	ABCOEFGHIJKL • • • • • • • • • • • • • • • • • • •	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 40 of 71

Owner Name and Address: UniPeg Investments Inc PO Box 877 East Helena MT 59635 Phone: (406) 442-2332

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2508659	High Country Travel Plaza UST	3122 US Highway 12 E	Helena	59601	(406) 442-3259	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 07 Currently in Use	4526	6/19/1990 16 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 06 Currently In Use	4527	6/19/1990 16 / No	Diesel 10,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCD0FGHJJKU B DEF0HJJKU	Yes Yes Yes Yes
8 / 12 Currently in Use	4528	10/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKU B (DEFOHIJKU	Yes Yes Yes Yes
9 / 13 Currently in Use	4529	10/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
10 / 14 Currently in Use	4530	10/1/1996 09 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
11 / 15 Currently in Use	4531	10/1/1996 09 / No	Diesel 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH)JKL B DEFOH)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 41 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2508706	Town Pump Inc Helena 1	1202 Prospect Ave	Helena	59601		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2506	4/15/1983 23 / No	Gasoline 12,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H J J K L B D E F • H J J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	2507	4/15/1983 23 / No	Gasoline 12,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	B DEF®HIJKL	Yes Yes Yes Yes
3 / 03 Currently in Use	2508	4/15/1983 23 / No	Gasoline 12,000	STI-P3 Impressed Current	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGH))(C) (B (DEFOH))(C)	Yes Yes Yes Yes
7 / 07 Currently In Use	2509	11/1/1998 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH) (KL B (DEFOH) (KL	Yes Yes Yes Yes
8 / 08 Currently In Use	2510	11/1/1998 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHUJKU B DEFOHUJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 42 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2508707	Town Pump Inc Helena 2	1140 Euclid Ave	Helena	59601		

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently in Use	4832	4/14/1984 22 / No	Diesel 6,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC●EFGHIJKL B ●EFGHI●KL	Yes Yes Yes Yes
4 / 04 Currently in Use	4833	7/1/1991 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGHIJKU	Yes Yes Yes Yes
5 / 05 Currently in Use	4834	7/1/1991 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	<pre>ABC●EFGHIJKL ● EFGHIJKL</pre>	Yes Yes Yes Yes
6 / 06 Currently in Use	4835	7/1/1991 15 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 43 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2508708	Town Pump Inc Helena 3	847 11th Ave	Helena	59601	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	2515	4/15/1971 35 / No	Gasoline 10,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	ABC • E F G H J K L B • E F G H J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	2516	4/15/1971 35 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Fiberglass Reinforced Plastic None	Pressurized	(ABCOEFGH))KL (BOEFGH))KL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 44 of 71

Owner Name and Address: Exxon Company USA 3120 US Highway 12 E Helena MT 59601 Phone: (406) 442-4190

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2508728	Exxon Marketing Helena Terminal	3120 US Highway 12 E	Helena	59601	(406) 442-4190	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
8 / S08 Currently in Use	2775	1/1/1950 56 / Ye	Diesel 638,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>ABCDEFGHIJ®L</pre>	Yes Yes Yes Yes
9 / S09 Currently in Use	2776	1/1/1950 56 / Ye	Diesel 638,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>ABCDEFGH()</pre> DEFGH()	Yes Yes Yes Yes
10 / S07 Currently in Use	2774	1/1/1950 56 / Ye	Diesel 638,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>ABCDEFGHIJ@L</pre>	Yes Yes Yes Yes
11 / S06 Currently in Use	2773	1/1/1950 56 / Ye	Gasoline 1,200,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>ABCDEFGHIJ€L</pre>	Yes Yes Yes Yes
12 / S05 Currently in Use	2772	1/1/1950 56 / Ye	Gasoline 1,200,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>ABCDEFGH()</pre> DEFGH()	Yes Yes Yes Yes
13 / S04 Currently in Use	2771	1/1/1950 56 / Ye	Gasoline 604,044	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	(ABCDEFGHIJEL (DEFGHIJEL	Yes Yes Yes Yes
14 / S03 Currently in Use	2770	1/1/1950 56 / Ye	Gasoline 604,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	ABCDEFGHIJOL	Yes Yes Yes Yes
15 / S02 Currently in Use	2769	1/1/1950 56 / Ye	Gasoline 603,330	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	(ABCDEFGH)J(L) (DEFGH)J(L)	Yes Yes Yes Yes


Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 45 of 71

16 / S01 Currently in Use	2768 1/1/1950 56 / Ye	Gasoline 603,330	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	<pre>ABCDEFGHIJEL</pre>	Yes Yes Yes Yes
17 / S22	2787 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGHIJ&L	Yes
Currently in Use	19 / Ye	1,000	Impressed Current	Double-Walled		B DEF•HIJ&L	Yes Yes Yes
25 / S20	2785 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH10.L	Yes
Currently in Use	19 / Ye	3,000	Impressed Current	Double-Walled		B DEF.H10.KL	Yes Yes Yes
26 / S21	2786 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH10.L	Yes
Currently in Use	19 / Ye	1,000	Impressed Current	Double-Walled		B DEF.H10.KL	Yes Yes Yes
27 / S19	2784 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH1J&L	Yes
Currently in Use	19 / Ye	3,000	Impressed Current	Double-Walled		B DEF@H1J&L	Yes Yes Yes
28 / S18	2783 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH108L	Yes
Currently in Use	19 / Ye	3,000	Impressed Current	Double-Walled		B DEF@H10KL	Yes Yes Yes
29 / S17	2782 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH108L	Yes
Currently in Use	19 / Ye	10,000	Impressed Current	Double-Walled		B DEF@H10KL	Yes Yes Yes
30 / S15	2780 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH1J&L	Yes
Currently in Use	19 / Ye	10,000	Impressed Current	Double-Walled		B DEF•H1JKL	Yes Yes Yes
31 / S16	2781 1/1/1987	Hazardous	Asphalt Coated or Bare Steel	Flexible Plastic	Pressurized	ABCDEFGH()	Yes
Currently in Use	19 / Ye	10,000	Impressed Current	Double-Walled		B DEF.H()	Yes Yes Yes
32 / 14	2767 1/1/1987	Mixture	Cathodically Protected Steel	Bare Steel	Gravity Feed	ABCDEF.H.1.K.L	Yes
Currently in Use	19 / No	2,000	Double-Walled	Cathodically Protected		B. DEF.G.H.1.K.L	Yes Yes Yes

Tank/Piping Release Detection Codes



Report Generation Date: 7/3/2006 Page 46 of 71

33 / S12 Currently In Use	2779 1/1/1950 56 / Ye	Gasoline 633,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	ABCDEFGHIJQL DEFGHIJQL	Yes Yes Yes Yes
35 / S11 Currently in Use	2778 1/1/1950 56 / Ye	Gasoline 633,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	(ABCDEFGH)J.L • DEFGH)J.R.L	Yes Yes Yes Yes
36 / S10 Currently in Use	2777 1/1/1950 56 / Ye	Diesel 638,000	Asphalt Coated or Bare Steel Impressed Current	Bare Steel Impressed Current	Pressurized	(ABCDEFGHIJ&L) (DEFGHIJ&L)	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 47 of 71

Owner Name and Address: Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2508775	Qwest Helena Main Central Office	441 N Park Ave	Helena	59601		

TankID/Alt TankID Status	Tag Installe Numbe Age/AS		Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option Piping Type		Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	1728 1/1/1992 14 /	Diesel No 2,500	Fiberglass Reinforced Plastic Double-Walled	Bare Steel Double-Walled/Non-Corro	U.S. Suction	B DEF.H.J.K.L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 48 of 71

Owner Name and Address: Qwest Communications 1600 7th Ave Room 2206 Seattle WA 98191 Phone: (206) 346-7532

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2508790	Qwest Helena Garage	1021 Chestnut St	Helena	59601	(406) 441-7728	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
2 / 02 Currently in Use	1729	11/1/1992 13 / No	Gasoline 6,000	Fiberglass Reinforced Plastic Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	ABCDEF.H.I.J.K.L.	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 49 of 71

Owner Name and Address: City of Helena 316 N Park Ave Helena MT 59623 Phone: (406) 447-1520

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2508813	10 Mile Water Treatment Facility	1115 Rimini Dr	Helena	59601	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	644 9/1/1991 14 / No	Diesel 1,000	STI-P3 Double-Walled	Bare Steel Cathodically Protected	Safe Suction	ABCDEF.H.I.J.K.L. • DEF.H.I.J.K.L.	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 50 of 71

Owner Name and Address: Hi Noon Petroleum PO Box 7578 Missoula MT 59807 Phone: (406) 532-0384

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2509772	Noons 422	1801 Cedar St	Helena	59601	(406) 443-3532

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Temporarily Out of U		2/10/1971 35 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic None	Pressurized		Yes Yes Yes Yes
2 / 02 Temporarily Out of U		2/10/1971 35 / No	Gasoline 8,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic None	Pressurized	<pre></pre>	Yes Yes Yes Yes
4 / 04 Temporarily Out of U		2/9/1973 33 / No	Gasoline 6,000	Cathodically Protected Steel Lined Interior/Impressed Curr	Flexible Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
5 / 05 Temporarily Out of U		10/1/1991 14 / No	Gasoline 10,000	STI-P3 Impressed Current	Flexible Plastic None	Pressurized	ABC®EFGH1JKL ® ®EFGH1JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 51 of 71

Owner Name and Address: Myron D & Tamara B Laib 4960 N Montana Ave Helena MT 59602 Phone: (406) 443-1917

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2510981	Thrifty Gas and Grocery	405 W Lincoln Road	Helena	59602	(406) 458-9493

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Temporarily Out of U		4/26/1989 17 / No	Gasoline 6,000	STI-P3 None	Bare Steel Cathodically Protected	U.S. Suction	<pre>A • • D E F G H I J K L • D E F G H I J K L</pre>	Yes Yes Yes Yes
2 / 01 Temporarily Out of U		4/26/1989 17 / No	Gasoline 6,000	STI-P3 None	Bare Steel Cathodically Protected	U.S. Suction	<pre></pre>	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 52 of 71

Owner Name and Address: Federal Reserve Bank 100 Neill Ave Helena MT 59601 Phone: (406) 447-3940

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
2511291	Federal Reserve Bank Helena	100 Neill Ave	Helena	59601	(406) 447-3946	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / S1 Currently in Use	2322	10/1/1989 16 / No	Heating Oil 4,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABC ● EFGH1JRL ● ©EFGH1QRL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 53 of 71

Owner Name and Address: Cenex Petroleum Inc PO Box 64089 MS 535 Saint Paul MN 55164 Phone: (651) 355-5583

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2512353	Kum and Go Store 832	3100 N Montana Ave	Helena	59602	(406) 449-8766

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 03 Currently in Use	561	6/7/1991 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	(ABC) EFGH (JK) (D) (EFGH (JK)	Yes Yes Yes Yes
2 / 01 Currently in Use	559	6/7/1991 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes
3 / 02 Currently in Use	560	6/7/1991 15 / No	Gasoline 10,000	STI-P3 None	Fiberglass Reinforced Plastic None	Pressurized	ABCOEFGHIJKL • • EFGHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 54 of 71

Owner Name and Address: Ted Beck PO Box 4327 Helena MT 59604 Phone: (406) 443-6464

Sys Fac I Location Name Location Street Address Location City Zip Location Phone
2512834 Dr Ted Beck 27 Airport Road Helena 59601

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4444	9/1/1992 13 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC@EF@H)JKL (B) @EF@H)JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 55 of 71

Owner Name and Address: Watkins & Shepard Trucking PO Box 5328 Missoula MT 59806 Phone: (406) 728-6121

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2512917	Watkins & Shepard Trucking Helena	1500 Blaine St	Helena	59601	(406) 442-9536

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	4458	2/3/1993 13 / No	Used Oil 2,000	STI-P3 Double-Walled	Bare Steel Double-Walled/Non-Corro	Gravity Feed	ABC • E F • H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	4459	2/3/1993 13 / No	Used Oil 500	STI-P3 Double-Walled	Bare Steel Double-Walled/Non-Corro	Gravity Feed	(ABCOEFOH) JKL (B DEFOH) JKL	Yes Yes Yes Yes
3 / 03 Currently in Use	4460	11/1/1995 10 / No	Diesel 12,000	Composite (Steel w/ FRP) Double-Walled	Fiberglass Reinforced Plastic Double-Walled	Pressurized	(ABCOEFOH) JKL (B DEFOH) JKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 56 of 71

Owner Name and Address: Merritt & Marie LLC 5295 York Road Helena MT 59602 Phone: (406) 227-5357

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2513657	Lakeside General Store	5330 York Road	Helena	59602	(406) 227-5357

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	4552	7/24/1995 10 / No	Gasoline 5,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(A (O (B (B (H ()) (K ()) () () () () () ()	Yes Yes Yes Yes
2 / 01 Currently in Use	4553	7/1/1995 11 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Fiberglass Reinforced Plastic None	Pressurized	(A	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 57 of 71

Owner Name and Address: Grimes Auto Dealership PO Box 6549 Helena MT 59604 Phone: (406) 442-5810

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2513687	Grimes Auto Dealership	3401 US Highway 12 E	Helena	59601	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	1244	3/15/1996 10 / No	Used Oil 8,000	STI-P3 Double-Walled	Bare Steel Double-Walled/Non-Corro	U.S. Suction	ABCDEF®HIJKL B DEF®HIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 58 of 71

Owner Name and Address: Sleeping Giant Pizza LLC 3425 US Highway 12 E Helena MT 59601 Phone: (406) 443-5050

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2513763	CENEX EZ Stop East	3425 US Highway 12	Helena	59601	(406) 442-4410

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently in Use	365	10/1/1996 09 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently in Use	366	10/1/1996 09 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF 6 H 1 J & L	Yes Yes Yes Yes
3 / 03 Currently in Use	4333	10/1/1996 09 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJ&U B DEFOHIJ&U	Yes Yes Yes Yes
4 / 04 Currently in Use	368	10/1/1996 09 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 59 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone	
5613818	Town Pump Inc Helena 6	2401 N Montana Ave	Helena	59601	(406) 443-5068	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4610	9/1/1997 08 / No	Gasoline 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF B H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	3443	10/1/1997 08 / No	Gasoline 15,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H 1 J K L B D E F • H 1 J K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 60 of 71

Owner Name and Address: Department of Military Affairs PO Box 4789 Fort Harrison MT 59636 Phone: (406) 841-3000

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613821	Army Aviation Support Facility	3333 Skyway Dr	Helena	59602	(406) 324-3047

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	827	3/1/1997 09 / No	Other 25,000	Fiberglass Reinforced Plastic Double-Walled	No Piping None	Pressurized	ABC • E F • H 1 J K L B D E F G H 1 J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	828	3/1/1997 09 / No	Other 25,000	Fiberglass Reinforced Plastic Double-Walled	No Piping None	Pressurized	ABC • E F • H 1 J & L B D E F G H 1 J & L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 61 of 71

Owner Name and Address: David and Debbie Clemens 4990 N Montana Helena MT 59602 Phone: (406) 449-9667

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613828	Daves EZ Stop Inc	4990 N Montana Ave	Helena	59602	(406) 442-7703

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	372	1/30/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABC • E F G H I J K L B D E F • H I J K L	Yes Yes Yes Yes
2 / 02 Currently In Use	373	1/30/1998 08 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF BH 1 J K L	Yes Yes Yes Yes
3 / 03 Currently In Use	374	1/30/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC • E F G H () K L B D E F • H () K L	Yes Yes Yes Yes
4 / 04 Currently In Use	375	1/30/1998 08 / No	Diesel 5,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABC • EF GH () K L B D E F • H () K L	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 62 of 71

Owner Name and Address: Mergenthaler Transfer & Storage 1430 Carter Drive Helena MT 59601 Phone: (406) 443-7964

Sys Fac I	Location Name	Location Street Address	Location	on City Zip	Location Phone	
5613831	Mergenthaler Transfer & Storage Carter	1430 Carter Dr	Helena	59601	(406) 443-7964	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	1609 1	11/1/1997 08 / No	Used Oil 3,000	STI-P3 Double-Walled	Flexible Plastic Double-Walled	Gravity Feed	ABCDEF®HIJKU B DEF®HIJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred	
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed	

Report Generation Date: 7/3/2006 Page 63 of 71

Owner Name and Address: Town Pump Inc PO Box 6000 Butte MT 59701 Phone: (406) 497-6700

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613846	Town Pump Inc Helena 4	2900 N Montana Ave	Helena	59601	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	2680	6/16/1998 08 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	2681	6/16/1998 08 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKU	Yes Yes Yes Yes
3 / 03 Currently In Use	2682	6/16/1998 08 / No	Gasoline 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKU B (DEFOHIJKU	Yes Yes Yes Yes
4 / 04 Currently In Use	2683	6/16/1998 08 / No	Diesel 6,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOH)J&L (B DEFOH)J&L	Yes Yes Yes Yes
5 / 05 Currently In Use	2684	7/24/1998 07 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
6 / 06 Currently In Use	4671	9/7/2001 04 / No	Diesel 8,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	Not Listed

Report Generation Date: 7/3/2006 Page 64 of 71

Owner Name and Address: Don & Barb Hulett 5850 York Road PO Box 4508 Helena MT 59602 Phone: (406) 443-3060

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613934	Eastside Fuel Stop	3044 10th Ave	Helena	59601	(406) 443-3060

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4145	5/1/1999 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	4146	5/1/1999 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF9H1JKL	Yes Yes Yes Yes
3 / 03 Currently In Use	4147	5/1/1999 07 / No	Gasoline 8,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently In Use	4148	5/1/1999 07 / No	Gasoline 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
5 / 05 Currently In Use	4149	5/1/1999 07 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B (DEFOHIJKL	Yes Yes Yes Yes
6 / 06 Currently In Use	4150	5/1/1999 07 / No	Diesel 12,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	(ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	I SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 65 of 71

Owner Name and Address: New Albertsons Inc PO Box 20 Boise ID 83726 Phone: (208) 395-6200

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5613956	Albertsons Express 2004	600 N Fee St	Helena	59601	(406) 442-1052

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4128	10/1/1999 06 / No	Gasoline 15,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	4129	10/1/1999 06 / No	Gasoline 10,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	(ABCOEFOHIJKL B OEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 66 of 71

Owner Name and Address: Safeway Stores Inc 1121 124th Ave NE Bellevue WA 98005 Phone: (425) 455-6545

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614000	Safeway Gasoline Helena	611 N Montana Ave	Helena	59601	(406) 442-6631

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01 Currently In Use	4330	6/1/2001 05 / No	Gasoline 20,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	8 DEFOHIJKL	Yes Yes Yes Yes
2 / 02 Currently In Use	4331	6/1/2001 05 / No	Gasoline 10,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	B DEFOHIJKU	Yes Yes Yes Yes
3 / 03 Currently In Use	4332	6/1/2001 05 / No	Diesel 10,000	Composite (Steel w/ FRP) Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCOEFOHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 67 of 71

Owner Name and Address: Sprint Communications Co LLP 6480 Sprint Pkwy 5B874 Overland Park KS 66251 Phone: (913) 315-8631

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
5614011	Sprint Helena POP	1100 Phoenix Ave	Helena	59601	

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 01	4322 6/1/2001	Diesel	Fiberglass Reinforced Plastic	Flexible Plastic	Pressurized	ABCOEFGHIJKL	Yes
Currently In Use	05 / No	2,500	Double-Walled	Double-Walled		B DEFOHIJKL	Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Causing	C Inventory Control	- Vapor Manitoring	G Interstit, Dbl-Wall Monitor	SIR	K Deferred
A Manual Tank Gauging	, , , , , , , , , , , , , , , , , , , ,	E Vapor Monitoring			K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	■ Not Listed
					· · · · · · · · · · · · · · · · · · ·

Report Generation Date: 7/3/2006 Page 68 of 71

Owner Name and Address: Mountain View Coop 2200 Old Havre Highway Lincoln MT 59639 Phone: (406) 453-5900

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2503995	Mountain View Coop Lincoln	525 Main Street lot 155 Lincoln Villa Sites	Lincoln	59639	

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 07 Currently in Use	2255	7/1/1996 10 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
5 / 04 Currently in Use	2252	7/1/1996 10 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	B DEF . H 1 J K L	Yes Yes Yes Yes
6 / 05 Currently in Use	2253	7/1/1996 10 / No	Gasoline 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
7 / 06 Currently in Use	2254	7/1/1996 10 / No	Diesel 12,000	STI-P3 None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 69 of 71

Owner Name and Address: Paul D & Cheryl D Beister PO Box 198 Wolf Creek MT 59648 Phone: (406) 235-4111

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2504132	Canyon Store Exxon	175 Recreation Road	Wolf Creek	59648	(406) 235-4111

TankID/Alt TankID Status	Tag Numbe	Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
3 / 03 Currently In Use	3483	11/30/1998 07 / No	Gasoline 3,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHIJKL B DEFOHIJKL	Yes Yes Yes Yes
4 / 04 Currently In Use	3484	11/30/1998 07 / No	Gasoline 7,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	B DEF 6 H 1 J K L	Yes Yes Yes Yes
5 / 05 Currently In Use	3946	11/30/1998 07 / No	Diesel 4,000	Fiberglass Reinforced Plastic None	Flexible Plastic Double-Walled	Pressurized	ABCOEFGHUJKU B DEFOHUJKU	Yes Yes Yes Yes

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 70 of 71

Owner Name and Address: Holter Lake Recreation Inc dba The 3000 Division Road Great Falls MT 59404 Phone: (406) 452-3622 Boat Loft

Dual Lu

Sys Fac I	Location Name	Location Street Address	Location City	Zip	Location Phone
2505921	Boat Loft	1460 Beartooth Road	Wolf Creek	59648	(406) 452-3622

TankID/Alt TankID Status	Tag Installed Age/AST	Product Capacity	Tank Mat'l of Construction Secondary Option	Piping Material Secondary Option	Piping Type	Tank Release Detection Piping Release Detection	FR Met Spill/OverI/C
1 / 02 Currently in Use	473 4/1/1993 13 / No	Gasoline 4,000	Fiberglass Reinforced Plastic Double-Walled	Flexible Plastic Double-Walled	Pressurized	ABCDEF.H.J.K.(B.DEF.H.J.K.(

Tank/Piping Release Detection Codes

A Manual Tank Gauging	C Inventory Control	E Vapor Monitoring	G Interstit. Dbl-Wall Monitor	SIR	K Deferred
B Tank/Line Tightness Testing	D ATG/Auto Line LD	F GW Monitoring	H Interstit. Sec. Con. Monitor	J Other Methods	L Not Listed

Report Generation Date: 7/3/2006 Page 71 of 71